

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,727,627 B1
APPLICATION NO. : 10/019286
DATED : April 27, 2004
INVENTOR(S) : K. Sasaki et al.


Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 36, claim 14 should read – The synchronous motor as claimed in claim 1, wherein the slots positioned adjacent to the center points of the rotor magnetic poles having shorter radial lengths than the slots positioned adjacent to the end points of the rotor magnetic poles.

Signed and Sealed this

Twenty-second Day of August, 2006



JON W. DUDAS
Director of the United States Patent and Trademark Office